Work Order	ID	57598
------------	----	-------

Quality Control



Page 1

Insp.

Stamp

Friday, April 09, 2010 1:31:48 PM Item ID: D3836-041 Accept Setup Start **Revision ID:** Stop Rib Assembly (Basket Lid, LH) Item Name: **Start Date:** 4/12/2010 Start Qty: 2.00 **Cust Item ID:** Req'd Qty: 2.00 Required Date: 4/15/2010 **Customer:** Reference: Run Start mF Date: 10-4-9. Tooling: Process Plan: Approvals: Date: Stop QC: Date: _____ SPC(Y/N): Date: Sequence ID/ Operation Set Up/ Draw Plan Accept Reject Draw Reject Work Center ID Number **Description Run Hours** Number Rev. Code Qty Qty **Draw Nbr Revision Nbr** D3836 Rev A 100 0.00 Large Fab Large Fab 0.00 Memo Large Fab 1- cut D3836-1 and D3836-3 rib as per dwg D3836 2- remove identification markings 3- deburr 10-04-19 4- weld D3836-1 to D3836-3 and drill hole (3/16") using DT9447 jig and open to finish size as per dwg D3836 5- weld D2327-3 spacer bushing as per dwg D3836 A/R ER316 S.S. Rod Batch: 11/679 6- grind weld flush where indicated on dwg 130 QC9- Inspect visual per QSI004- Fusion Welds 0.00 10.04.30 0.00

Memo

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	iES	- N			
DATE	STEP	PR	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			•						
Part No	:	PAR #-	Fault Cated	iorv.	NCB: V	as No	DOA:	Date	
			Fault Category: NCR: Yes No DQA: Date: Disposition: QA: N/C Closed: Date:						
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)			CO. Turk
DATE	STEP	Description of NC		ion B	Ve	rification	Approval	Approval	
	J.L.	Section A					Section C	Chief Eng	QC Inspector
									_

^{*} H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Work Order ID 57598

Friday, April 09, 2010 1:31:48 PM



Page 2

Item ID:

D3836-041

Accept

Setup Start



Revision ID:

Item Name:

Required Date: 4/15/2010

Rib Assembly (Basket Lid, LH)

Start Date:

4/12/2010

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

Process Plan:

Date: _____

Date: Tooling:

SPC (Y/N):

0.00

0.00

0.00

Date:

Date:

Draw

Rev.

Plan

Code

Run

Start

Stop

Stop



Sequence ID/

Work Center ID

140

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Memo

Memo

Set Up/ **Run Hours**

Accept

Oty

Reject Oty

Reject Number

Insp. Stamp

150

Packaging

Packaging

Identify as per dwg & Stock Location: & A

160

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/04/20 10 MF, n-4-20

Dart	Aer	nen	ace	l td
Dail	ACI.	USU	auc	Lu

	-								
W/O:			W	ORK ORDER CHANGES	<u> </u>			***************************************	
DATE	STEP	PROC	EDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	-								
Part No	:	PAR #:	_ Fault Cate	gory:	NCR: Yes	No DQ	A :	_ Date: _	
		esolution:							
NCR:		W	ORK ORD	ER NON-CONFORMAN	CE (NCR)			-
DATE	STEP	Description of NC	Corrective Action Section B			Verific	ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	& Section C		Chief Eng	QC Inspector
		·							-
		·					:		
·								:	
									<u> </u> -

^{&#}x27; H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

Picklist Print

Friday, April 09, 2010 1:31:47 PM

Work Order ID: 57598

Parent Item:

D3836-041

Parent Item Name:

Rib Assembly (Basket Lid, LH)

Comments:

IPP Rev:A 08-12-01 new issue DD verified by:EC



Start Date: 4/12/2010

Required Date: 4/15/2010

Page 1

Start Otv: 2.00

Required Oty: 2.00

Comments:	PP Rev:A 08-12-	·01 new issue D	D veri	ned by:EC				2	Start Qty: 2.00		Required Qty: 2	.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2327-3 Spacer Bushing		Manufactured	No			100	Each	31.0000	2.0000	711	Eplic.	4.19
V				Warehoo Loca		Loc	<u>Oty</u>	Loc Code			,	
*	•			Main Wa WA	rehouse		31					
					55917 57186		11 20		_	2	-	
M304TS0.750W.065		Purchased	No	_		100	f	362.8531	3.7491	SAD	10-0	4-19
				Wareho Loca		Loc	<u>Otv</u>	Loc Code				

 Warehouse
 Loc Oty
 Loc Code

 Location
 ...

 Main Warehouse
 ...

 WA
 362.8530684

 111148
 58


 113956
 23.5

 114137
 281.353068

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A: Date:					
		esolution:										
NCR:		\	WORK ORI	DER NON-CONFORM	ANCE (NCF	R)						
DATE	STEP	Description of NC Section A	Initial	ion B Sign &	Verific		Approval	Approval				
		Section A	Chief Eng	Action Description Chief Eng	Date	Section	on C	Chief Eng	QC Inspector			
		,							-			
									<u>.</u>			


H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



Dart Aerospace Ltd


	•								
W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									
Part No	Part No: PAR #:		Fault Cat	A:	Date:				
- "	R	esolution:	Dispositi	on:	QA: N/C CI	osed:		Date: _	·
NCR:		,	WORK ORI	DER NON-CONFORMA	NCE (NCF	R)			
DATE	STED	Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval
·	SILP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Chief Eng	QC Inspector
									-
T.									
									·
								!	
									<u>.</u>

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



W/O:			WC	BES	S							
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
_		c.							1 Too Mg			
										•		
									•			
Part No: PAI		PAR #:	Fault Cate	gory:	_ NCR	: Yes N	lo DQ/	A:	Date:			
			Disposition: QA: N/C Closed: Date:									
NCR:			WORK ORDI	ER NON-CONFORM	ANCE	(NCR)		******				
DATE	STEP	Description of NC		tion B		Verific	ation	Approval	Approval			
DAIL	OIL!	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng			
				•						_		
			ı i		ı		1			I.		

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



		— - - -									
W/O:			V	VORK O	RDER CHANGI	ES					· · ·
DATE	STEP	PROCEDURE CHANGE					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			٠.			;					
·											- 14 K
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	····								_
		PAR #:	_ Fault Ca		NCR	_ Date: _	ate:				
	R	esolution:	_ Disposi	tion:		_ QA: i	WC Clo	sed:		Date:	
NCR:		W	ORK OR	DER NO	N-CONFORMA	NCE	(NCR)	·			
DATE	STEP	Description of NC	Corrective Action Section			Varii			fication Approval	Annroval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Ad	ction Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
				·.			****				
								,			

^{*} H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE